ਦਫਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119 Email ID :- xen.mansa@gmail.com

ਪੱਤਰ ਨੰ..1122 ਮਿਤੀ.....04/06/2025

ਵੱਲ,

Principal,

Royal Convent School,

Sardulgarh (Mansa).

ਵਿਸ਼ਾ: ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ। (ਸਾਲ 2025-26)

ਹਵਾਲਾ: ਆਪ ਦਾ Ref. No. RCS/25/193 ਮਿਤੀ 04/04/25 ਦੇ ਸਬੰਧ ਵਿੱਚ।

ਤੁਹਾਡੇ ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਦੇ ਦਫਤਰ ਵੱਲੋਂ ਵਿਜੂਅਲੀ ਇੰਸਪੈਕਸ਼ਨ ਕੀਤੀ ਗਈ ਅਤੇ ਉਹਨਾ ਦੀ ਰਿਪੋਰਟ/ਸਿਫਾਰਿਸ਼ ਅਨੁਸਾਰ ਨਿਮਨਲਿਖਤ ਨਿਰੀਖਣਾਂ ਅਤੇ ਸ਼ਰਤਾਂ ਅਧੀਨ ਸਾਲ 2025-26 ਦਾ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਮਿਤੀ 31-03-2026 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

1) ਇੰਜ. ਆਸ਼ੂਤੋਸ਼ ਮਿੱਤਲ ਵੱਲੋਂ ਮਿਤੀ 29-04-2025 ਨੂੰ ਸਟਰੱਕਚਰ ਸੁਰੱਖਿਆ ਸਰਟੀਫਿਕੇਟ ਦਿੱਤਾ ਗਿਆ ਹੈ ਅਤੇ ਉਹਨਾ ਦੇ ਸਰਟੀਫਿਕੇਟ ਅਨੁਸਾਰ ਸਕੂਲ ਸੈਸ਼ਨ 2025-26 ਲਈ ਵਰਤੋਂ ਲਈ ਸੁਰੱਖਿਅਤ ਹੈ, ਪਰੰਤੂ ਇਸ ਸਕੂਲ ਦਾ ਨਿਰਮਾਣ ਇਸ ਵਿਭਾਗ ਵੱਲੋਂ ਨਹੀਂ ਕੀਤਾ ਗਿਆ ਹੈ, ਇਸ ਲਈ ਇਸ ਵਿਭਾਗ ਦੁਆਰਾ ਸਕੂਲ ਦੇ ਸਟਰੱਕਚਰ ਦੀ ਸੇਫਟੀ ਖਾਸ ਕਰਕੇ ਭੂਚਾਲ ਦੇ ਦ੍ਰਿਸ਼ਟੀਕੋਣ ਤੋਂ ਯਕੀਨੀ ਨਹੀਂ ਬਣਾਈ ਜਾ ਸਕਦੀ ਹੈ।

2) ਜੇਕਰ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਇਮਾਰਤ ਵਿੱਚ ਕੋਈ ਵਾਧਾ, ਤਬਦੀਲੀ, ਵਿਸਤਾਰ ਅਤੇ ਸੋਧ ਦੀ ਲੋੜ ਹੈ ਜਾ ਕੀਤੇ ਜਾਣੇ ਹਨ ਤਾ ਇਸ ਦਫਤਰ ਦੀ ਤੁਰੰਤ ਜਾਂਚ ਦਾ ਪ੍ਰਬੰਧ ਕੀਤਾ ਜਾਣਾ ਚਾਹੀਦਾ ਹੈ ਅਤੇ ਉਸ ਹਿੱਸੇ ਨੂੰ ਮੁਕੰਮਲ ਕਰਕੇ ਉਸ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਇਸ ਦਫਤਰ ਪਾਸੋਂ ਫਿਰ ਤੋਂ ਲਿਆ ਜਾਵੇ।

3) ਜੇਕਰ ਬਿਲਡਿੰਗ ਦੀਆਂ ਕੰਧਾ, ਨੀਹਾਂ ਅਤੇ ਛੱਤਾਂ ਕੁਦਰਤੀ ਆਫਤ ਜਾ ਕਿਸੇ ਹੋਰ ਕਾਰਨ ਕਰਕੇ ਬੈਠ ਜਾਣ ਤਾ ਇਸ ਸੂਰਤ ਵਿੱਚ ਸਕੂਲ ਵੱਲੋਂ ਇਸ ਦਫਤਰ ਨੂੰ ਤੁਰੰਤ ਬਿਲਡਿੰਗ ਦੀ ਹਾਲਤ ਬਾਰੇ ਸੂਚਿਤ ਕੀਤਾ ਜਾਵੇ ਅਤੇ ਨਿਰੀਖਣ ਕਰਵਾਉਣ ਉਪਰੰਤ ਹੀ ਬਿਲਡਿੰਗ ਨੂੰ ਵਰਤੋਂ ਵਿੱਚ ਲਿਆ ਜਾਵੇ।

4) ਸਬੰਧਤ ਵਿਭਾਗ ਤੋਂ ਵੱਖਰੇ ਤੌਰ ਤੇ ਫਾਇਰ ਸੇਫਟੀ ਅਤੇ ਬਿਜਲੀ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਪ੍ਰਾਪਤ ਕੀਤਾ ਜਾਵੇ।

5) ਸਕੂਲ ਬਿਲਡਿੰਗ ਦੀ ਸੇਫਟੀ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਬਿਲਡਿੰਗ ਦੀ ਰਿਪੇਅਰ ਕਰਵਾਉਣ ਦੀ ਜਿੰਮੇਵਾਰੀ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਦੀ ਹੈ। ਇਸ ਰਿਪੋਰਟ ਦੇ ਬਾਵਜੂਦ ਸਕੂਲ ਪ੍ਰਬੰਧਨ ਸਾਰੇ ਪੱਖਾਂ ਤੋਂ ਬਿਲਡਿੰਗ ਦੀ ਸੁਰੱਖਿਆ ਲਈ ਜਿੰਮੇਵਾਰ ਹੈ।

6) ਸਕੂਲ ਕੋਲ ਕਿਸੇ ਅਣਸੁਖਾਵੀਂ ਆਪਦਾ ਨਾਲ ਨਜਿੱਠਣ ਲਈ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ ਦੌਰਾਨ ਬੱਚਿਆ ਨੂੰ ਬਿਲਡਿੰਗ ਵਿਚੋਂ ਸੁਰੱਖਿਅਤ ਬਾਹਰ ਕੱਢਣਾ ਅਤੇ ਸਬੰਧਤ ਵਿਭਾਗ ਨਾਲ ਤਾਲਮੇਲ ਕਰਨ ਦੀ ਯੋਜਨਾ ਹੋਣੀ ਚਾਹੀਦੀ ਹੈ। ਸਕੂਲ ਨੂੰ ਇਸ ਯੋਜਨਾ ਦੀ ਪ੍ਰਭਾਵਸ਼ੀਲਤਾ ਨੂੰ ਯਕੀਨੀ ਬਣਾਉਣ ਲਈ ਨਿਯਮਿਤ ਤੌਰ 'ਤੇ ਸਮੀਖਿਆ ਅਤੇ ਅੱਪਡੇਟ ਕਰਦੇ ਰਹਿਣਾ ਚਾਹੀਦਾ ਹੈ।

7) ਪੰਜਾਬ ਸਰਕਾਰ ਦੀਆਂ ਹਦਾਇਤਾਂ ਮੁਤਾਬਕ ਰੋਡ ਟੂ ਅਸੈਸ ਦੀ ਮੰਨਜੂਰੀ ਸਬੰਧਤ ਵਿਭਾਗ ਤੋ ਲੈਣ ਲਈ ਸਕੂਲ ਪ੍ਰਬੰਧਕ ਖੁਦ ਜਿੰਮੇਵਾਰ ਹੋਵੇਗਾ।

8) ਸਕੂਲ ਨੂੰ ਸਟਾਫ ਮੈਂਬਰਾਂ ਨੂੰ ਉਚਿਤ ਸੁਰੱਖਿਆ ਸਿਖਲਾਈ ਪ੍ਰਦਾਨ ਕਰਨੀ ਚਾਹੀਦੀ ਹੈ, ਜਿਸ ਵਿੱਚ ਐਮਰਜੈਂਸੀ, ਫਸਟ ਏਡ ਅਤੇ ਨਿਕਾਸੀਪ੍ਰੋਟੋਕੋਲ ਨੂੰ ਸੰਭਾਲਣ ਦੀਆਂ ਪ੍ਰਕਿਰਿਆਵਾਂ ਵੀ ਸ਼ਾਮਲ ਹਨ।

9) ਸਕੂਲ ਦੇ ਕਵਰਡ ਏਰੀਏ ਦੇ ਹਿਸਾਬ ਨਾਲ ਜੀ.ਆਰ ਨੰ. 4628759 ਮਿਤੀ: 27/05/2025 ਰਾਹੀਂ ਦਸ ਹਜਾਰ ਰੁਪਏ (10,000/-) ਬਿਲਡਿੰਗ ਨਿਰੀਖਣ ਫੀਸ ਵਜੋਂ ਪ੍ਰਾਪਤ ਕੀਤੇ ਗਏ।

10) ਇਹ ਰਿਪੋਰਟ ਕਾਨੂੰਨੀ ਉਦੇਸ਼ ਲਈ ਵੈਲਿਡ ਨਹੀਂ ਹੈ।

ਨੱਥੀ: ਨਕਸ਼ਾ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।
ਮਿਤੀ

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ.2, ਮਾਨਸਾ ਨੂੰ ਉਹਨਾ ਦੇ ਪੱਤਰ ਨੰ. 146 ਮਿਤੀ 29/05/2025 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਿਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

Head Mistress
Royal Convent School
Sardulgarh (Mansa)

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।

Office: Executive Engineer, Provincial Board Public Works Department Buildings and Roads Branch, Mansa.

Telephone/ Fax No : 01652-232119 Email ID:xen.mansa@gmail.com Latter No..1122 Date 04/06/25

Reference:

Principal
Royal Convent School,
Sardulgarh, Distt. Mansa..

NOTARY
SANT RAM
GURWAN
Dist. Mansa
Regd. No.
GOVT. OF INDIA

Regarding Issuance of Building Safety Certificate (Year 2025-26)

You are here Ved.. RC/25/193 dated 04/04/25.

Your school building has been visually inspected by the office of Sub-Divisional Engineer and as per their report/recommendation School Building Safety Certificate for the year 2025-26 dated 31-03-2026 subject to the following observations and conditions

Issued up to:-

1. Structure Safety Certificate has been issued by Mr. Asutos Mittal dated 29.04-2025 and according to his certificate the school is safe for use for the session 2025-26, but the construction of this school by this department has not been done, therefore the safety of the school structure especially from the seismic point of view cannot be ensured by this department.
2. If any addition, alteration, extension and modification is required or to be done by the school in this building, then an immediate inspection should be arranged by this office and its safety certificate should be obtained again from this office after completion of that part.
3. If the walls, foundations and roofs of the building collapse due to natural calamity or any other reason, then the school should immediately inform this office about the condition of the building and the building should be put into use only after conducting an inspection.
4. Fire safety and electrical safety certificate should be obtained separately from the concerned department.
5. Keeping the safety of the school building in mind, it is the responsibility of the school management to repair the building. Despite this report, the school management is responsible for the security of the building in all respects.
6. The school should have a plan to deal with any untoward incident, including the safe evacuation of children from the building during an emergency and a plan to coordinate with the concerned department. The school should regularly review and update this plan to ensure its effectiveness.
7. According to the instructions of the Punjab government, the school administrator himself will be responsible for getting the road to assessment approval from the concerned department.

Head Mistress
Royal Convent School
Sardulgarh (Mansa)

Certified that this Certificate/Document is TRABSLATED From Punjabi Language to English Language US 8(1)(h) of Notaries act 1952 (India)

8. The school must provide staff members with appropriate safety training, including procedures for handling emergencies, first aid and evacuation protocols.
9. According to the covered area of the school, GR no. 4628759 Dated: 27/05/2025 received ten thousand rupees (10,000/-) as building construction fee.
10. This report is not valid for legal purpose.

Attached : Map

Executive Engineer, Provincial
Board B&M Branch, Mansa

number no.

The above is copied from Sub Divisional Engineer, Provincial Sub Division No. 2 Branch Mansa vide their letter no. 146 dated 29/05/2025, it is written that building safety certificate is issued to the said school keeping your recommendation in mind.

Executive Engineer, Provincial
Board B&M Branch, Mansa

NOTARY
SANT RAM
GURWAN
Dist. Mansa
Regd. No.
9812
GOVT. OF INDIA

Attested as identified
SANT RAM GURWAN
NOTARY
Distt. Mansa (Pb.)
9.6.2025

Head Mistress
Royal Convent School
Sardulgarh (Mansa)

Certified that this Certificate/Document
is TRABSLATED From Punjabi
Language to English Language US
8(1)(h) of Notaries act 1952 (India)